

IMPORTANT — To assure product **SAFETY** and **RELIABILITY**, repairs, maintenance or adjustments should be performed by **MAKITA** Service Centers or other qualified service organizations. Always use **MAKITA** replacement parts.




Fig.	Part No.	Used	Description	Fig.	Part No.	Used	Description
1	911156-3	4	SCREW M4X30	28	*	1	HEX SOCKET HEAD BOLT
2	156725-5	1	GEAR HOUSING	29	311500-8	1	YOKE
3	211029-3	1	BALL BEARING 627	30	*	1	HEX NUT
4	253823-7	1	WASHER 7	31	251986-3	1	SCREW M6X6
5	331151-1	1	ROD	32	911158-9	2	SCREW M4X30
6	212063-6	1	NEEDLE BEARING 1012	33	411827-7	1	MOTOR HOUSING COVER
7	253758-2	1	WASHER 10	34	911131-9	2	SCREW M4X18
8	153138-1	1	CRANK SHAFT	35	687001-1	1	STRAIN RELIEF
9	253715-0	1	WASHER 6	36	643550-8	2	BRUSH HOLDER CAP
10	156731-0	1	GEAR HOUSING COVER (With Needle Bearing 212011-5)	37	643053-2	2	CARBON BRUSH (CB-53)
11	211033-2	1	BALL BEARING 608LB	38	651817-0	1	SWITCH
12	241081-7	1	FAN	39	953106-2	2	RIVET
13	611431-4	1	ARMATURE ASSEMBLY (Assembled fig. 11-15)	41	**	1	MOTOR HOUSING (With 2 ea. BRUSH HOLDER 643557-4)
14	681614-0	1	INSULATION WASHER	42	682500-8	1	CORD GUARD
15	211028-5	1	BALL BEARING 627LB	43	654018-9	2	GARTER SPRING
16	621416-2	1	FIELD ASSEMBLY (With fig. No. 43)	44	664013-1	1	CORD With Plug (2X18X8, SJT)
17	263002-9	1	RUBBER PIN 4	45	232062-2	1	LEAF SPRING
18	**	2	**	46	961017-7	1	STOP RING
19	263002-9	1	RUBBER PIN 4	47	341651-3	1	SWITCH LEVER
20	256110-3	1	PIN 6	48	256626-8	1	PIN 4
21	913427-4	1	SCREW M8X16	49	411784-9	1	SAFETY LOCK
22	341676-7	1	PROTECTOR	55	410048-8	1	WRENCH HOLDER
23	942101-7	1	WASHER 5				
24	922207-7	1	BOLT M5X10				
25	321311-3	1	BLADE HOLDER				
26	253334-2	0-3	WASHER 5				
27	922112-8	1	BOLT M4X10				
				ACCESSORIES			
				401	783201-2	1	HEX WRENCH 3
				402	*	2	SHEAR BLADE

*SEE SERVICE CHANGE 1
** SEE SERVICE CHANGE 2

SERVICE CHANGE

1. Changes on Shear Blade.




Fig. 402 is threaded.

Fig.	Description	Type 1	Type 2
28	Hex Socket Head Bolt	Part #922137-2 (Size:M4x20)	Part #922127-5 (Size:M4x16)
30	Hex Nut	Part #252036-7	—————
402	Shear Blade	Part #191384-8 (Discontinued)	Part #191384-8A

The above parts are completely interchangeable as a set.

SERVICE CHANGE

2. Change on Motor Housing




Fig.	Description	Type 1	Type 2
18	_____	Part #925183-4 Hex Bolt M4x55	Part #265891-8 Tap Screw M4x55
41	Motor Housing	Part #156766-1 (Discontinued)	Part #157720-8

The above parts are completely interchangeable as a set.

SALEX